

**1999  
STANDARD  
DIARY**

**Daily Reminder**

KCslip4 63258

SEA431349

E MARGINAL

KCslip4 63259

SEA431350

**NAME**

**ADDRESS**

TEL.

**FRIDAY**

1

JANUARY

**1999**      1st day – 364 days follow

## New Year's Day

SEA431351

JANUARY

2

SATURDAY

New Year's Bank Holiday (Scotland) 1999

2nd day - 363 days follow

SUNDAY

3

JANUARY

1999

3rd day - 362 days follow

A-A-GLANCE®

KCslip4 63261

SEA431352

JANUARY 4 MONDAY

1999 4th day - 361 days follow

1415 - Telemetry on Scada  
1430 was failed at WP  
found no telemetry failure  
at E. man.

Jack Lewis

1400 Station check test, send  
arms, hose pump room,  
D yarn

TUESDAY 5 JANUARY

1999 5th day - 360 days follow

SEA431353

KCslip4 63262

JANUARY

6

WEDNESDAY

1999 6th day - 359 days follow

1108 - Station check  
Change filter in  
Ventilation Unit.  
1135 - Tim T

THURSDAY

7

JANUARY

1999 7th day - 358 days follow

SEA431354

KCslip4 63263

JANUARY 8 FRIDAY

1999 8th day - 357 days follow

0735 - Station Check Panga  
Bubble's, West Wall Level  
at 94.9

0830 - Tim T

SATURDAY 9 JANUARY

1999 9th day - 356 days follow

■ ~~NOTES~~ ■

KCslip4 63264

SEA431355

JANUARY **10** SUNDAY

1999 10th day - 355 days follow

MONDAY **11** JANUARY

1999 11th day - 354 days follow

9:50 Checked and tested UPS. Sync  
1330 station log list.  
Send alarms, hose  
Pump 1000  
D Yards

KCslip4 63265

SEA431356

JANUARY

**12**

TUESDAY

1999 12th day – 353 days follow

WEDNESDAY

**13**

JANUARY

1999 13th day – 352 days follow

© AT-A-GLANCE®

KCslip4 63266

SEA431357

JANUARY

14

THURSDAY

1999 14th day - 351 days follow

1100 - station check, penguin done  
w/w, 1 penguin on  
10 years

FRIDAY

15

JANUARY

1999 15th day - 350 days follow

1235 - Station Check  
- Penguin Bubble is  
- Wet Line Level - 94.9  
1330 - 1 in T

KCslip4 63267

SEA431358

JANUARY **16** SATURDAY

SUNDAY **17** JANUARY

1999 16th day - 349 days follow

1999 17th day - 348 days follow

SEA431359

KCslip4 63268

JANUARY **18** MONDAY

Martin Luther King, Jr. Day (US) 1999 18th day - 347 days follow

TUESDAY **19** JANUARY

1999 19th day - 346 days follow

1325 - Station Check first

- Sent Alvaro's, Ferran
- Bullock's door check.
- Recharge Hydro Tank.
- Outside Lamping.
- Exercise Instruments Note
- Test Standing float.
- 1450 - End of

KCslip4 63269

SEA431360

JANUARY

**20**

WEDNESDAY

1999 20th day - 345 days follow

THURSDAY

**21**

JANUARY

1999 21st day - 344 days follow

KCslip4 63270

SEA431361

JANUARY **22** FRIDAY

1999 22nd day - 343 days follow

0950 - Station Check.

- Garage Bulbkin's

- Wet Well Level  $\rightarrow$  94.9

0940 - T = T

SATURDAY **23** JANUARY

1999 23rd day - 342 days follow

SEA431362

KCslip4 63271

JANUARY **24** SUNDAY

1999 24th day - 341 days follow

MONDAY **25** JANUARY

1999 25th day - 340 days follow

A&A CLANCE

KCslip4 63272

SEA431363

JANUARY **26** TUESDAY

Australia Day (Australia) 1999 26th day - 339 days follow

0830 Lube Rep Units  
- Sabour

1340 WORKING ON BACKFLOW  
PREVENTER

PAOLA

1500 - Took Sample from  
Wet Well, Bad Odor  
Solvent on Chemical  
Took Sample to Lab.  
1515 - T = 1

WEDNESDAY **27** JANUARY

1999 27th day - 338 days follow

1450 - Station check Punga  
Bubbly "No Bad Odor"  
Wet Well Level at 94.9  
1525 - T = 1

ADV-BLANCE®

KCslip4 63273

SEA431364

JANUARY **28** THURSDAY

1999 28th day - 337 days follow

FRIDAY **29** JANUARY

1999 29th day - 336 days follow

2-3-1

1330 - Station Check.  
Pings, Bubbles, What  
Wind level at 95.0  
Test Run RSP's

1405 - Tim T

KCslip4 63274

SEA431365

JANUARY **30** SATURDAY

1999 30th day - 335 days follow

SUNDAY **31** JANUARY

1999 31st day - 334 days follow

SEA431366

KCslip4 63275

FEBRUARY

1

MONDAY

1999 32nd day - 333 days follow

12:30 Departed el. C. M. Kynd

~~1400~~

1400 Changed Chart.

Jackson Lewis

TUESDAY

2

FEBRUARY

1999 33rd day - 332 days follow

1200 Station check list  
Send garns  
Send down w/ car  
Tool storage, house  
Pond room

9.YAKWU

KCSlip4 63276

SEA431367

FEBRUARY

3

WEDNESDAY

1999 34th day - 331 days follow

THURSDAY

4

FEBRUARY

1999 35th day - 330 days follow

1250 - Station check  
Water level at 94.9  
Buoy Bubble's  
1315 - T-T

KCslip4 63277

SEA431368

FEBRUARY

5

FRIDAY

1999 36th day – 329 days follow

SATURDAY

6

FEBRUARY

1999 37th day – 328 days follow Waitangi Day (New Zealand)

AT A GLANCE

KCslip4 63278

SEA431369

FEBRUARY

7

SUNDAY

1999 38th day - 327 days follow

MONDAY

8

FEBRUARY

1999 39th day - 326 days follow

KCslip4 63279

SEA431370

FEBRUARY 9 TUESDAY

1999 40th day - 325 days follow

2-9-99- 0930 station check list  
Send alarms, hose pump  
room

D Yoder

1400 - Sent alarms.

1415 Jack Lewis

WEDNESDAY 10 FEBRUARY

1999 41st day - 324 days follow

SEA431371

KCslip4 63280

FEBRUARY

11

THURSDAY

1999 42nd day - 323 days follow

0700 station check, pumps  
down way, try  
pumps in high  
D [unclear]

FRIDAY

12

FEBRUARY

1999 43rd day - 322 days follow

Lincoln's Birthday (US)

0700 station check for  
long weekend  
D [unclear]

SEA431372

KCslip4 63281

FEBRUARY

13

SATURDAY

1999 44th day - 321 days follow

SUNDAY

14

FEBRUARY

1999 45th day - 320 days follow

Valentine's Day (US, C, UK)

✓ AEROLINCE 9

KCslip4 63282

SEA431373

FEBRUARY 15 MONDAY

Washington's Birthday,

1999 46th day - 319 days follow

Observed (US)

TUESDAY 16 FEBRUARY

1999 47th day - 318 days follow

1430 - Check station,  
Send Alarms

OY/B.F.

KCslip4 63283

SEA431374

FEBRUARY **17** WEDNESDAY

Ash Wednesday 1999 48th day - 317 days follow

THURSDAY **18** FEBRUARY

1999 49th day - 316 days follow

13:15 - check station.  
B.F.

KCslip4 63284

SEA431375

FEBRUARY **19** FRIDAY

1999 50th day - 315 days follow

1100- Station check for Reworked

Trust

SATURDAY **20** FEBRUARY

1999 51st day - 314 days follow

SEA431376

KCslip4 63285

FEBRUARY **21** SUNDAY

1999 52nd day - 313 days follow

MONDAY **22** FEBRUARY

1999 53rd day - 312 days follow

© AT-A-GLANCE®

KCslip4 63286

SEA431377

FEBRUARY **23** TUESDAY

1999 54th day - 311 days follow

Crave inspection - Sarah White  
FT Crave

Looked at configuration to  
make for easier / safer access

10:00 - 10:45

1400 Station check  
O. Hause

WEDNESDAY **24** FEBRUARY

1999 55th day - 310 days follow

Working on Rain Gauge  
System

KCslip4 63287

SEA431378

FEBRUARY 25 THURSDAY

1999 56th day - 309 days follow

0810 - IN STATION TO REPAIR  
GRATE (MOTOR Room)  
(Need Bolts & adapter) *Barney*  
Be Back

Checking for proposed crane rail  
from hatch to door LESNIK

1100 station check, Run pump  
in hand, purged cable  
& pump

1040 Back to work on grating  
*Barney*

1210 - Verify sump pump operation. Runs -

FRIDAY 26 FEBRUARY

1999 57th day - 308 days follow

10:00 AM TO PM  
Batteries Add'd water +  
Cleaned, Gelled AND  
Adjusted Charger  
P.T. Batteries ON "12 hr" E  
Charge Tom Blue 1"

1330 STATION check for forward.

*Mark*

✓ APPROVED

KCslip4 63288

SEA431379

FEBRUARY

**27**

SATURDAY

1999 58th day - 307 days follow

SUNDAY

**28**

FEBRUARY

1999 59th day - 306 days follow

KCslip4 63289

SEA431380

MARCH

1

MONDAY

1999 60th day - 305 days follow

TUESDAY

2

MARCH

1999 61st day - 304 days follow

1010- changed chart.

Jackie Lewis

KCslip4 63290

SEA431381

MARCH 3 WEDNESDAY

1999 62nd day - 303 days follow

1020 - ~~Check~~ Sump Pump installation  
Sump

1020 - ~~Check~~ Sump Pump installation  
Sump

1030 - Check Sump Pump installation  
Sump

1230 - Station check, fixed  
+ cleaned #2 pump  
fixed C2 water system  
& yard

THURSDAY 4 MARCH

1999 63rd day - 302 days follow

0730 - Check Station  
Cleared root drain.  
Shut off w/w ~~loop~~  
Exhaust Fan. (Broken belt)  
will report. B.F.

SEA431382

KCSlip4 63291

MARCH 5 FRIDAY

1999 64th day - 301 days follow

1020 - Station check for the weekend.  
Mark

SATURDAY 6 MARCH

1999 65th day - 300 days follow

© AFA GLANCE

KCslip4 63292

SEA431383

MARCH 7 SUNDAY

1999 66th day - 299 days follow

MONDAY 8 MARCH

1999 67th day - 298 days follow

1490 station check list send  
alarms, hose pump from  
D Yabu

KCslip4 63293

SEA431384

MARCH

9

TUESDAY

1999 68th day - 297 days follow

0920 - Cleaning, dusting  
control & motor rooms,  
will wet mopp later.  
B.F.

WEDNESDAY

10

MARCH

1999 69th day - 296 days follow

KCslip4 63294

SEA431385

MARCH

11

THURSDAY

1999 70th day - 295 days follow

11:00 - Check Stations  
B.T.

FRIDAY

12

MARCH

1999 71st day - 294 days follow

KCslip4 63295

SEA431386

MARCH **13** SATURDAY

1999 72nd day - 293 days follow

SUNDAY **14** MARCH

1999 73rd day - 292 days follow

Mothering Sunday  
(United Kingdom)

KCslip4 63296

SEA431387

MARCH **15** MONDAY

Canberra Day (Australia) 1999 74th day - 291 days follow

12:00 - Station checklist,  
Send Alarms. B.F.

TUESDAY **16** MARCH

1999 75th day - 290 days follow

SEA431388

KCslip4 63297

MARCH **17** WEDNESDAY

St. Patrick's Day (Ireland, US) 1999 76th day - 289 days follow

0945 IN STATION TO CHECK  
WET WELL EXHAUST FAN  
Barney

THURSDAY **18** MARCH

1999 77th day - 288 days follow

0845- Check Station.

KCslip4 63298

SEA431389

MARCH **19** FRIDAY

1999 78th day - 287 days follow

1000 - Station check for the weekend.

*Musk*

SATURDAY **20** MARCH

1999 79th day - 286 days follow

KFA-GLENCO

KCslip4 63299

SEA431390

MARCH **21** SUNDAY

1999 80th day - 285 days follow

MONDAY **22** MARCH

1999 81st day - 284 days follow

1330 station check light  
Send alarm, clear  
basement, jump train  
& return

KCslip4 63300

SEA431391

MARCH **23** TUESDAY

1999 82nd day - 283 days follow

WEDNESDAY **24** MARCH

1999 83rd day - 282 days follow

KCslip4 63301

SEA431392

MARCH **25** THURSDAY

1999 84th day - 281 days follow

1400 station check from  
pump in hand  
D Yarn

FRIDAY **26** MARCH

1999 85th day - 280 days follow

Check Rain Gauge

Papert

HIS - Station check for the weekend

Mark

KCslip4 63302

SEA431393

MARCH **27** SATURDAY

1999 86th day - 279 days follow

SUNDAY **28** MARCH

1999 87th day - 278 days follow

Palm Sunday

In Station with Phon  
Co To Check SCAD  
CRT

Ryton

AFA-GLANCE

KCslip4 63303

SEA431394

MARCH **29** MONDAY

1999 88th day - 277 days follow

12:45- Station check list  
Send Alarms, recharge  
Hydro Tank.

B.F.

TUESDAY **30** MARCH

1999 89th day - 276 days follow

DATA GLANCE®

KCslip4 63304

SEA431395

MARCH 31 WEDNESDAY

Passover begins at sundown 1999 90th day - 275 days follow

700 Mechanical PM we  
couldn't get the outside supply  
to start.

1000 - changed chart.  
Jacket lines

THURSDAY 1 APRIL

1999 91st day - 274 days follow Passover

0945- Check Station.

B.F.

SEA431396

KCslip4 63305

APRIL

2

FRIDAY

Good Friday

1999

92nd day - 273 days follow

SATURDAY

3

APRIL

1999 93rd day - 272 days follow

1045 - start deck for Howard.

Mark

KCslip4 63306

SEA431397

APRIL **4** SUNDAY

Easter Sunday 1999 94th day - 271 days follow  
Daylight Saving Time begins (US)

MONDAY **5** APRIL

1999 95th day - 270 days follow Easter Monday (C, UK, A, NZ)

1300 - Station checklist.  
Send alarms to W.R.  
Test follow RSP's. B.F.

KCSlip4 63307

SEA431398

APRIL

6

TUESDAY

1999 96th day - 269 days follow

WEDNESDAY

7

APRIL

1999 97th day - 268 days follow

VERA GLANCE®

KCslip4 63308

SEA431399

APRIL **8** THURSDAY

1999 98th day - 267 days follow

1015 IN TO REPLACE  
Toilet Seat - leave  
For belt  
Boat

1115 - Check Station,  
B.F.

FRIDAY **9** APRIL

1999 99th day - 266 days follow

1200 - Station check for the weekend.

*[Signature]*

KCslip4 63309

SEA431400

APRIL **10** SATURDAY

1999 100th day - 265 days follow

SUNDAY **11** APRIL

1999 101st day - 264 days follow

KCslip4 63310

SEA431401

APRIL **12** MONDAY

1999 102nd day - 263 days follow

'500 - checked station - C)

TUESDAY **13** APRIL

1999 103rd day - 262 days follow

SEA431402

KCslip4 63311

APRIL

14

WEDNESDAY

1999 104th day - 261 days follow

0815 - Insurance inspection-Brown & Caldwell

Milk

1330 - station check list

Send alarms purged  
bubbler

D farm

THURSDAY

15

APRIL

1999 105th day - 260 days follow

1200- Station check

Milk

KCslip4 63312

SEA431403

APRIL **16** FRIDAY

1999 106th day - 259 days follow

0635 Here to PM.  
Slip Rings & Brusher  
Tom Flar. 11

~~0815 Cleaned out strainer~~

SATURDAY **17** APRIL

1999 107th day - 258 days follow

AT-A-GLANCE

KC Slip 4 63313

SEA431404

APRIL **18** SUNDAY

1999 108th day - 257 days follow

MONDAY **19** APRIL

1999 109th day - 256 days follow

1400 - Station check list  
Send alarms  
D Yards

KCslip4 63314

SEA431405

APRIL **20** TUESDAY

1999 110th day - 255 days follow

0815 - station check list  
Send alarms, cleaned  
out strainers on sea  
water took # 2 back  
to Janeson will return  
to day

D Yarn  
all back together  
D Yarn

WEDNESDAY **21** APRIL

1999 111th day - 254 days follow

Professional Secretaries

Day® (US)

SEA431406

KCslip4 63315

APRIL **22** THURSDAY

1999 112th day - 253 days follow

1140 - Check Station,  
B.F.

FRIDAY **23** APRIL

1999 113th day - 252 days follow

0140 - Ashford EFC. - Replace overloads in  
sump pump MCC bucket - Burns - Clear 755

0635 - Station check for the weekend - The wet well  
really struck today!

Mark

KCslip4 63316

SEA431407

APRIL **24** SATURDAY

1999 114th day - 251 days follow

SUNDAY **25** APRIL

1999 115th day - 250 days follow

Anzac Day (A, NZ)

ZEPHYRUS

KCslip4 63317

SEA431408

APRIL **26** MONDAY

1999 116th day - 249 days follow

9:50 Wiegeman ASSET TAGS.  
10:05 out Ld

1200 - station check list, some  
alarm pump down  
w/w lose D Yelmo

TUESDAY **27** APRIL

1999 117th day - 248 days follow

1845 PM SITION  
Batteries + Charger  
Tom Elwell

A LA GLANCE

KCslip4 63318

SEA431409

APRIL **28** WEDNESDAY

National Day of Mourning (Canada) 1999 118th day - 247 days follow

THURSDAY **29** APRIL

1999 119th day - 246 days follow

0920 - check station  
B.F.

KCslip4 63319

SEA431410

APRIL **30** FRIDAY

1999 120th day - 245 days follow

1300 - Station deck for the weekend  
*Murphy*

SATURDAY **1** MAY

1999 121st day - 244 days follow

SEA431411

KCslip4 63320

MAY **2** SUNDAY

1999 122nd day - 243 days follow

MONDAY **3** MAY

1999 123rd day - 242 days follow May Day (United Kingdom)

1015 - changed chart.

Jackie Lewis

1130 - station check. List several alarms, pump down well & hose out, hosed down pump room

D. Yarow

KCslip4 63321

SEA431412

MAY **4** TUESDAY

1999 124th day - 241 days follow

WEDNESDAY **5** MAY

1999 125th day - 240 days follow

✓ ARA GLANCE

KCslip4 63322

SEA431413

MAY **6** THURSDAY

1999 126th day - 239 days follow

0930 - CHICK STATION  
R.F.

PRINT INTO PRESSURE WASH EXT.  
OF BLDG

Eggs

FRIDAY **7** MAY

1999 127th day - 238 days follow

1030 - Station chick to the island  
Arab

POWER INTO PREP BLDGS  
Eggs

PRINTER LEFT 5 GALLONS  
OF WATER SEALER HERE FOR  
FUTURE USE.

Eggs

KCslip4 63323

SEA431414

MAY

8

SATURDAY

1999 128th day - 237 days follow

SUNDAY

9

MAY

1999 129th day - 236 days follow

Mother's Day (US, C)

KCslip4 63324

SEA431415

MAY 10 MONDAY

1999 130th day - 235 days follow

11:00 - Station checklist,  
Send Alarms to W.P. Recharged  
c-2 hydro tank, pump down w/p  
B.F.

TUESDAY 11 MAY

1999 131st day - 234 days follow

0715 Head to P.M.  
STATION Tom Elwell  
Printed into prime EXT.  
Lynn

KCslip4 63325

SEA431416

MAY **12** WEDNESDAY

1999 132nd day - 233 days follow

0650 IN STATION WITH  
ENGINEER FOR LIFT  
UPGRADE

FT CROWN engineer  
Ed HAHNE

GREEN  
BARNETT  
LESNIAC

1030 Here To PM.

STATION

Tue Elve 11

Pointer into parrot ext.

Elvie

THURSDAY **13** MAY

1999 133rd day - 232 days follow

100 - station check pump  
down up, legal bush  
D Yawn

KCslip4 63326

SEA431417

MAY **14** FRIDAY

1999 134th day - 231 days follow

SATURDAY **15** MAY

1999 135th day - 230 days follow Armed Forces Day (US)

Wrote into prime Ext  
English

1030 - session due for the weekend.

Mark

A-A-GLANCE®

KCslip4 63327

SEA431418

MAY 16 SUNDAY

1999 136th day - 229 days follow

MONDAY 17 MAY

1999 137th day - 228 days follow

1300 station check list sent  
alarms purged bubbles,  
hosed pump room, ran  
seeps in hand  
D Yarn

KCslip4 63328

SEA431419

MAY **18** TUESDAY

1999 138th day - 227 days follow

Painted into Finish prime  
Ext.

WEDNESDAY **19** MAY

1999 139th day - 226 days follow

Painted into paint ext.  
Ext.

KCslip4 63329

SEA431420

MAY **20** THURSDAY

1999 140th day - 225 days follow

Printed into print ext.  
Tyco  
0900 - Check station, dumped  
trash  
D Yarn

1235 - Check Station. B.F.

FRIDAY **21** MAY

1999 141st day - 224 days follow

Printed into print ext.  
Tyco  
1150 checking station  
Spac & Charles

AT-A-GLANCE

KCslip4 63330

SEA431421

MAY **22** SATURDAY

1999 142nd day - 223 days follow

SUNDAY **23** MAY

1999 143rd day - 222 days follow

AT-A-GLANCE<sup>®</sup>

KCslip4 63331

SEA431422

MAY **24** MONDAY

Victoria Day (Canada)

1999 144th day - 221 days follow

TUESDAY **25** MAY

1999 145th day - 220 days follow

10:00 - STATION CHECK LIST  
Send Alarms. adjust \*1  
RT packing, clean mess. B.F.

Painted up to paint ext. letters  
Eyes

© ADABLANC INC.

KCslip4 63332

SEA431423

MAY **26** WEDNESDAY

1999 146th day - 219 days follow

10 AM Painter into paint ext  
Tylor

THURSDAY **27** MAY

1999 147th day - 218 days follow

Paint in to Paint point  
Elec. Box & gas line &  
remove masking  
Tylor

1400 - Check station  
CW/SL

✓ AIA GLANCE

KCslip4 63333

SEA431424

MAY **28** FRIDAY

1999 148th day - 217 days follow

0930 - Changed the chart

Jacki Lewis

SATURDAY **29** MAY

1999 149th day - 216 days follow

KCslip4 63334

SEA431425

MAY **30** SUNDAY

1999 150th day - 215 days follow

MONDAY **31** MAY

1999 151st day - 214 days follow Memorial Day, Observed (US)

Spring Bank Holiday

(United Kingdom)

KCslip4 63335

SEA431426

JUNE **1** TUESDAY

1999 152nd day - 213 days follow

0830 - CHECKED SERVICE A.C.'S  
S. GREENE

1400 - Station check list,  
Seal alarms to C.P.  
Adjust #1 RSP packing, flushed drain  
& sump. Hospital pump room.  
B.F.

WEDNESDAY **2** JUNE

1999 153rd day - 212 days follow

Checking FT Crane Crane modification  
proposals LESNIK BARNEY NORMAN BROOKS GREEN

KCslip4 63336

SEA431427

JUNE

3

THURSDAY

1999 154th day - 211 days follow

0950- Check Station  
BF

FRIDAY

4

JUNE

1999 155th day - 210 days follow

1000 hrs STATION CHECK  
Cheng

KCslip4 63337

SEA431428

JUNE **5** SATURDAY

1999 156th day - 209 days follow

SUNDAY **6** JUNE

1999 157th day - 208 days follow

A-GLEANCE®

KCslip4 63338

SEA431429

JUNE 7 MONDAY

Holiday (Ireland)

1999 158th day - 207 days follow

1230 - Check Station Seal  
Alarms to W.P. Switched Rst  
Leads to 3-2-1 R.F.

TUESDAY 8 JUNE

1999 159th day - 206 days follow

0130 - AT station to test  
Mobil generator on station load  
for tomorrow's power outage.  
B.F./D.Y./S.G./L.P./

KCslip4 63339

SEA431430

JUNE 9 WEDNESDAY

1999 160th day - 205 days follow

0845 - Station on generator power for the day for Settle City light work on E. Main Wy.

D.Y./B.F.

0900 CHECKING GEN SET  
S.GREENE

0900 Luke station fence & chg oil in Chassis

1530 - Power back on line  
B.F., D.Y.

THURSDAY 10 JUNE

1999 161st day - 204 days follow

0700 - checking station returned Gen truck to Duranish.

D.Y./B.F.

©AGLANCE'S

KCslip4 63340

SEA431431

JUNE **11** FRIDAY

1999 162nd day - 203 days follow

SATURDAY **12** JUNE

1999 163rd day - 202 days follow

AFAGLANCE

KCslip4 63341

SEA431432

JUNE **13** SUNDAY

1999 164th day – 201 days follow

MONDAY **14** JUNE

1999 165th day – 200 days follow

Flag Day (US)

AT-A-GLANCE®

KCslip4 63342

SEA431433

JUNE 15 TUESDAY

1999 166th day - 199 days follow

0700 Station check list  
Send alarme, house  
cleaning, hose pump  
room  
D Yarnell

13:15 Checked and tested UPS.  
" and cleaned station  
batteries, set charger on equalizing  
charge.  
Kym

WEDNESDAY 16 JUNE

1999 167th day - 198 days follow

SEA431434

KCslip4 63343

JUNE **17** THURSDAY

1999 188th day - 197 days follow

12:00 - Check thy station  
B.F.

FRIDAY **18** JUNE

1999 189th day - 196 days follow

SEA431435

KCslip4 63344

JUNE **19** SATURDAY

1999 170th day - 195 days follow

SUNDAY **20** JUNE

1999 171st day - 194 days follow Father's Day (US, C, UK)

ASSISTANCE

KCslip4 63345

SEA431436

JUNE **21** MONDAY

1999 172nd day - 193 days follow

1230 - Station checklist,  
Send Alarms, Exercised  
int. gate.

R.F.

TUESDAY **22** JUNE

1999 173rd day - 192 days follow

0815 REPLACED BELTS ON  
SERVICE A.C'S

S. GREENE & J. BOWEN

KCslip4 63346

SEA431437

JUNE

23

WEDNESDAY

1999 174th day - 191 days follow

THURSDAY

24

JUNE

1999 175th day - 190 days follow

St-Jean (Québec)

1430 - check station  
C/W B/F

KCSlip4 63347

SEA431438

JUNE **25** FRIDAY

1999 176th day - 189 days follow

STEVE 12:30 CHECKING PUAPS

SATURDAY **26** JUNE

1999 177th day - 188 days follow

ATA-GlANCE 8

KCslip4 63348

SEA431439

JUNE **27** SUNDAY

1999 178th day - 187 days follow

MONDAY **28** JUNE

1999 179th day - 186 days follow

SEA431440

KCslip4 63349

JUNE **29** TUESDAY

1999 180th day - 185 days follow

1200 - station check list  
Send alarms, pump  
those w/w, run pump  
in hand  
D.Y.

WEDNESDAY **30** JUNE

1999 181st day - 184 days follow

SEA431441

KCslip4 63350

JULY **1** THURSDAY

Canada Day (Canada) 1999 182nd day - 183 days follow

1430 - Check Station,  
B.F.

FRIDAY **2** JULY

1999 183rd day - 182 days follow

KCslip4 63351

SEA431442

JULY **3** SATURDAY

1999 184th day – 181 days follow

SUNDAY **4** JULY

1999 185th day – 180 days follow

Independence Day (US)

AT-A-GLANCE

KCslip4 63352

SEA431443

JULY **5** MONDAY

1999 186th day - 179 days follow

TUESDAY **6** JULY

1999 187th day - 178 days follow

1300 - Check Station Serial  
Alarms, Recharged Hydro  
TANK

B.F.

KCslip4 63353

SEA431444

JULY **7** WEDNESDAY

1999 188th day - 177 days follow

0930 - Found front gate  
wide open. Closed it, and  
relocked it. Nothing in log!  
B.F.

THURSDAY **8** JULY

1999 189th day - 176 days follow

SEA431445

KCslip4 63354

JULY **9** FRIDAY

1999 190th day - 175 days follow

SATURDAY **10** JULY

1999 191st day - 174 days follow

KCslip4 63355

SEA431446

JULY **11** SUNDAY

1999 192nd day - 173 days follow

MONDAY **12** JULY

1999 193rd day - 172 days follow

1400 - Check Station.  
P.B.F.

AKA-GLANCE®

KCslip4 63356

SEA431447

JULY **13** TUESDAY

1999 194th day - 171 days follow

live with KC Engineer Char Namine  
to discuss their concerns of pyro  
crane enhancements

LESNIK

WEDNESDAY **14** JULY

1999 195th day - 170 days follow

SEA431448

KCslip4 63357

JULY **15** THURSDAY

1999 196th day - 169 days follow

1130- Checked Station,  
B.F.

FRIDAY **16** JULY

1999 197th day - 168 days follow

KCslip4 63358

SEA431449

JULY

**17**

SATURDAY

1999 198th day - 167 days follow

SUNDAY

**18**

JULY

1999 199th day - 166 days follow

SEA431450

KCslip4 63359

JULY **19** MONDAY

1999 200th day - 165 days follow

11:00- Check station, Send  
ALARMS to W.P. Exercise  
All RSP's Switched RSP Leads  
to 2-3-1 #1 needs to be  
REPACKED or added to. Flushed  
#1 RSP packing drain, clean  
pump, Flushed pump.  
B.F.

TUESDAY **20** JULY

1999 201st day - 164 days follow

SEA431451

KCSlip4 63360

JULY **21** WEDNESDAY

1999 202nd day - 163 days follow

THURSDAY **22** JULY

1999 203rd day - 162 days follow

1300- Station check, cleared  
CO alarm  
D Yarn

KCslip4 63361

SEA431452

JULY **23** FRIDAY

1999 204th day - 161 days follow

SATURDAY **24** JULY

1999 205th day - 160 days follow

✓ AT-A-GLANCE®

KCslip4 63362

SEA431453

JULY **25** SUNDAY

1999 206th day - 159 days follow

MONDAY **26** JULY

1999 207th day - 158 days follow

1250 - Check Station,  
Send Alarms to W.P.  
B.F.

KCSlip4 63363

SEA431454

JULY **27** TUESDAY

1999 208th day - 157 days follow

WEDNESDAY **28** JULY

1999 209th day - 156 days follow

1030 cube RSP pumps, motors, and  
ducts

-S. Dyan

A-GLEANCE

KCslip4 63364

SEA431455

JULY **29** THURSDAY

1999 210th day - 155 days follow

FRIDAY **30** JULY

1999 211th day - 154 days follow

0900- changed the chart  
jelly lines

0630- Reset the retro fit  
telemetry failure  
jelly lines

1230 Check Station  
B-1

KCslip4 63365

SEA431456

JULY **31** SATURDAY

1999 212th day - 153 days follow

SUNDAY **1** AUGUST

1999 213th day - 152 days follow

KCslip4 63366

SEA431457

AUGUST

2

MONDAY

Civic Holiday (Canada)

1999 214th day - 151 days follow

Holiday (Ireland)

1200 - Check Station,  
Send Alarms to W.P.  
B.F.

993-7859

TUESDAY

3

AUGUST

1999 215th day - 150 days follow

0900 - Gated OUT #1 RSP  
for M. Green to REPACK, and  
inspect.  
B.F.

900 Repacked #1 RSP  
wear sleeve is in very good  
condition

1445 - AT STATION w/ generator truck  
Power outage caused by lightning.  
Station working fine on gen power  
with QC.S #2 RST on. ~~QC.S~~  
Station in LOCAL cont. PLC tripped,  
and went restart, called for inst. Tech

1700 - Power outage Relieved  
B.F. Called Electrician  
out. BACK ON LINE  
(@ MIDNIGHT)

Planned & Done

Disconnected CR180 on  
TRANSFER SWITCH SO PUMPS WILL RUN  
W/H REPAIR TOMORROW

Tom Elwell

KCSlip4 63367

SEA431458

AUGUST

4

WEDNESDAY

1999 216th day - 149 days follow

0630 working on Transistor  
Switch controls. Had  
Bad contact on CR 176.  
Moved wire's to Good  
contact on CR 176 Working  
OK.

T. Etw. 11  
G K, ac

Check RTU Alarm

Payton

THURSDAY

5

AUGUST

1999 217th day - 148 days follow

100 checked Station  
Spencer J

RTU OPERATION

AIA-BLANC

KCSlip4 63368

SEA431459

AUGUST **6** FRIDAY

1999 218th day - 147 days follow

1240 - C STATION WITH US WEST  
Spence J.

SATURDAY **7** AUGUST

1999 219th day - 146 days follow

SEA431460

KCslip4 63369

AUGUST

8

SUNDAY

1999 220th day - 145 days follow

MONDAY

9

AUGUST

1999 221st day - 144 days follow

1100 - station check list, send  
alarms, pump down when  
run pump in hard, lose  
pump room

D Yahn

VITA-GLENCE 10

KCslip4 63370

SEA431461

AUGUST

10

TUESDAY

1999 222nd day - 143 days follow

0915 - AT station to rec.  
U.S. West phone co.  
B.F.

1400 - On station to let U.S.  
West into station  
D. James

WEDNESDAY

11

AUGUST

1999 223rd day - 142 days follow

SEA431462

AUGUST

12

THURSDAY

1999 224th day - 141 days follow

1210 - Check Station  
BF

AT-A-GLANCE

## Time to Reorder

The best source is where you  
usually purchase stationery  
products.

If this product is not available  
locally, please use the reorder  
form on the next page.

KCslip4 63372

SEA431463

FRIDAY 13 AUGUST

1999 225th day - 140 days follow

0800 Station check  
Chayl

## 2000 ORDER FORM

Name \_\_\_\_\_ Last \_\_\_\_\_ First \_\_\_\_\_  
Address \_\_\_\_\_  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_  
Daytime Phone (\_\_\_\_\_) \_\_\_\_\_

If unable to obtain where you purchase  
stationery products, send entire page  
with payment (U.S. \$) in full to:

CALENDARS  
P O BOX 400  
SIDNEY, NY 13838

### PICK IN ALL INFORMATION BELOW

Quantity	Description	Price ea.	Extension
	SD387-13, Daily Reminder	\$28.35	

Shipping & Handling **\$4.95**

New York State residents must add sales tax

County \_\_\_\_\_ Add \$ \_\_\_\_\_

Offer not valid outside U.S.A. **TOTAL**

You can pay by check or credit card. Check applicable box:

Check (\$10.00 Service Charge on all returned checks)

Make checks payable to "CALENDARS"

MasterCard  Visa  Amer. Express Expiration Date \_\_\_\_\_

Card Number \_\_\_\_\_

Cardholder Name \_\_\_\_\_ (please print)

Signature \_\_\_\_\_

REMITTANCE IN ONE OF ABOVE FORMS MUST  
ACCOMPANY ORDER  
ALLOW 4 WEEKS FOR DELIVERY

DATA-GLEANER

KCslip4 63373

SEA431464

AUGUST

**14**

SATURDAY

1999 226th day - 139 days follow

SUNDAY

**15**

AUGUST

1999 227th day - 138 days follow

© AT-A-GLANCE

KCslip4 63374

SEA431465

AUGUST **16** MONDAY

1999 228th day - 137 days follow

1000 station deck list  
Sand charges, pump  
Down w/c  
D. Gahan

TUESDAY **17** AUGUST

1999 229th day - 136 days follow

Explain EWR for crane project to  
Engineer Hanath. LESNIAK

AT-A-GLANCE®

KCslip4 63375

SEA431466

AUGUST

18

WEDNESDAY

1999 230th day - 135 days follow

THURSDAY

19

AUGUST

1999 231st day - 134 days follow

0920 - Check Station.  
B.F.

© ARA-SOURCE

KCslip4 63376

SEA431467

AUGUST **20** FRIDAY

SATURDAY **21** AUGUST

1999 232nd day - 133 days follow

1999 233rd day - 132 days follow

© AMERICAN BRADLEY

KCslip4 63377

SEA431468

AUGUST **22** SUNDAY

1999 234th day - 131 days follow

MONDAY **23** AUGUST

1999 235th day - 130 days follow

1200 - Station checklist,  
Send alarms to W.P.  
Pump down wet well, flushed  
RSP packing drains, sump.  
B.F.

KCslip4 63378

SEA431469

AUGUST **24** TUESDAY

1999 236th day - 129 days follow

WEDNESDAY **25** AUGUST

1999 237th day - 128 days follow

1355 - Anthony Construction 1 Plumber  
Survey station for SEAL Water Repairs  
BURNS-WPMC Not Found (located sta 1450)

AT-A-GLANCE®

KCslip4 63379

SEA431470

AUGUST

**26**

THURSDAY

1999 238th day - 127 days follow

0845 - Check Station  
B.F.

FRIDAY

**27**

AUGUST

1999 239th day - 126 days follow

SEA431471

KCslip4 63380

AUGUST

**28**

SATURDAY

1999 240th day - 125 days follow

SUNDAY

**29**

AUGUST

1999 241st day - 124 days follow

KCslip4 63381

SEA431472

AUGUST **30** MONDAY

Summer Bank Holiday  
(United Kingdom)

1999 242nd day - 123 days follow

TUESDAY **31** AUGUST

1999 243rd day - 122 days follow

0800 - Let US West  
in station, Station check  
list, Send messages to W.P.  
Cleaning, Empty trash.  
B.F.

10:30 Checked and cleaned station  
batteries, set charger on equalizing  
charge!  
Hyatt

AIA-GLANCE®

KCslip4 63382

SEA431473

SEPTEMBER

1

WEDNESDAY

1999 244th day - 121 days follow

THURSDAY

2

SEPTEMBER

1999 245th day - 120 days follow

ATA BLANCES

KCslip4 63383

SEA431474

SEPTEMBER

3

FRIDAY

1999 246th day - 119 days follow

SATURDAY

4

SEPTEMBER

1999 247th day - 118 days follow

KCslip4 63384

SEA431475

SEPTEMBER

5

SUNDAY

1999 248th day – 117 days follow

MONDAY

6

SEPTEMBER

1999 249th day – 116 days follow

Labor Day (US, C)

A-G-LANCE®

KCslip4 63385

SEA431476

SEPTEMBER

7

TUESDAY

1999 250th day - 115 days follow

WEDNESDAY

8

SEPTEMBER

1999 251st day - 114 days follow

1245 - Checked Station  
Send Alarms to W.P.  
Adjusted #2 RSP packing,  
Flushed drain, and pump room  
Pump down w/p B.F.

AFAGLANCE

KCSlip4 63386

SEA431477

SEPTEMBER

9

THURSDAY

FRIDAY

10

SEPTEMBER

1999 252nd day - 113 days follow

1999 253rd day - 112 days follow

Rosh Hashanah

begins at sundown

0930 - Check Station

Contractors here digging up  
the driveway. No inspector,  
nothing in Log, no notification,  
notified offsite to find out  
what's going on.

B.F.

1900 - Station check

2 Yds

© 1999 AGENDA

KCSlip4 63387

SEA431478

SEPTEMBER

11

SATURDAY

Rosh Hashanah

1999 254th day – 111 days follow

SUNDAY

12

SEPTEMBER

1999 255th day – 110 days follow

KCslip4 63388

SEA431479

SEPTEMBER **13** MONDAY

1999 256th day - 109 days follow

1250 - Station checklist,  
Send alarms to W.P.  
Station very dusty from contract  
Recharge hydro tank. R.F.

1505-Verify equipment for Seal water  
Replacement Contract #C83210C-Bars

TUESDAY **14** SEPTEMBER

1999 257th day - 108 days follow

SEA431480

KCSlip4 63389

SEPTEMBER

15

WEDNESDAY

1999 258th day - 107 days follow

THURSDAY

16

SEPTEMBER

1999 259th day - 106 days follow

2845- Checked Station,  
B.F.

© AMARILLO

KCslip4 63390

SEA431481

SEPTEMBER **19** SUNDAY

Yom Kippur  
begins at sundown

1999 262nd day - 103 days follow

MONDAY **20** SEPTEMBER

1999 263rd day - 102 days follow

Yom Kippur

A-A-GLANCE®

KCslip4 63391

SEA431482

SEPTEMBER **21** TUESDAY

1999 264th day - 101 days follow

1500 - Checked Station,  
Send Alarms.  
B.F.

WEDNESDAY **22** SEPTEMBER

1999 265th day - 100 days follow

1450 - Called out by W.P.  
to put Test switch back  
to normal.  
B.F.

KCslip4 63392

SEA431483

SEPTEMBER **23** THURSDAY

1999 266th day - 99 days follow

FRIDAY **24** SEPTEMBER

1999 267th day - 98 days follow

AAGLANCE®

KCslip4 63393

SEA431484

SEPTEMBER **25** SATURDAY

1999 268th day - 97 days follow

SUNDAY **26** SEPTEMBER

1999 269th day - 96 days follow

AIR GLANCE

KCslip4 63394

SEA431485

SEPTEMBER

**27**

MONDAY

1999 270th day - 95 days follow

0000 - call-out from UPMC.

Found #2 Pump Kickout.

Reset #2 P4 Breaker - Pump

Seams - OK - "But" Switch

leads #2 in STBY Also

Sewage coming in to Station  
is very septic - Why?

Spence J.

0700 - Station check list,  
send alarms, rose

pump room, ran pump

#2 in hand per B.S.

put in lead for today  
D Yamas

1430 - AT STATION TO SWITCH

PUMP LEADS TO 3-2-1 FOR  
the night. B.F.

TUESDAY

**28**

SEPTEMBER

1999 271st day - 94 days follow

0730 - On station to switch  
leads #2 is an  
Open

SEA431486

SEPTEMBER

29

WEDNESDAY

1999 272nd day - 93 days follow

THURSDAY

30

SEPTEMBER

1999 273rd day - 92 days follow

10830 - Checked station,  
#2 RSP in lead. Good Amp,  
RPM<sup>2</sup>. Appears to be functioning  
fine. Left in lead position  
for the weekend

B.F.

© A.A. GLANCE®

KCslip4 63396

SEA431487

OCTOBER

1

FRIDAY

1999 274th day - 91 days follow

SATURDAY

2

OCTOBER

8:20

Let in CONCRETE CUTTERS  
UM + #111  
facilitate

1300 Start work for the weekend.

Reset C WATER ALARM?  
no contractors here! Also from  
contractors using too much water.

A-A-GLANCE

KCSlip4 63397

SEA431488

OCTOBER

3

SUNDAY

1999 276th day - 89 days follow

MONDAY

4

OCTOBER

1999 277th day - 88 days follow

Show Engineering Team Station for New  
Crane design. LESNIAT

DATA-SOURCE

KCslip4 63398

SEA431489

OCTOBER **5** TUESDAY

1999 278th day - 87 days follow

Checking Hoist

Ryan

Checking station, list, Sent  
Alarms

Espana/Charles

WEDNESDAY **6** OCTOBER

1999 279th day - 86 days follow

1000 - checking station for  
operation & cleaning needs  
of yard

KCslip4 63399

SEA431490

OCTOBER

7

THURSDAY

1999 280th day - 85 days follow

FRIDAY

8

OCTOBER

1999 281st day - 84 days follow

11:20 - Check Station.  
B.F.

AT-A-GLANCE®

KCslip4 63400

SEA431491

OCTOBER **9** SATURDAY

1999 282nd day - 83 days follow

SUNDAY **10** OCTOBER

1999 283rd day - 82 days follow

KCslip4 63401

SEA431492

OCTOBER **11** MONDAY

Columbus Day, Observed (US) 1999 284th day - 81 days follow

Thanksgiving Day (Canada)

11:35 Checked and cleaned slip rings  
replaced brushes for clutches on  
Q8P1 #1 + #2 + #3!  
Hypal

TUESDAY **12** OCTOBER

1999 285th day - 80 days follow

1340 - Check Station,  
Send ALARMS to W.P.  
B.E.

KCslip4 63402

SEA431493

OCTOBER

13

WEDNESDAY

1999 286th day - 79 days follow

THURSDAY

14

OCTOBER

1999 287th day - 78 days follow

3900 - Check Station, Clean  
up contractor mess.

B.F.

1000 - Checked metrotel "comm.  
fail". will call GTE.

Jacobsen

11:30 Checked watered and cleaned  
station batts, set chargers on  
equalizing charger.

Jyl

KCslip4 63403

SEA431494

OCTOBER **15** FRIDAY

1999 288th day - 77 days follow

SATURDAY **16** OCTOBER

1999 289th day - 76 days follow

National Boss Day (US)

KCslip4 63404

SEA431495

OCTOBER **17** SUNDAY

1999 290th day - 75 days follow

MONDAY **18** OCTOBER

1999 291st day - 74 days follow

SEA431496

KCslip4 63405

OCTOBER **19** TUESDAY

1999 292nd day - 73 days follow

0930- Station checklist  
Send Alarms to C.O.P.  
Pump down wet well. Cleaned  
motor room. Change S.F. FILTERS  
B.F.

WEDNESDAY **20** OCTOBER

1999 293rd day - 72 days follow

10M Rain gauge  
Rupture

1230 - Gated OFF & drained!  
#2 RSP for maint to repack!  
Suction, and discharge valves  
are open! Flushed #2 RSP  
packing drain. B.F.

KCslip4 63406

SEA431497

OCTOBER **21** THURSDAY

FRIDAY **22** OCTOBER

1999 294th day - 71 days follow

1240 - Checked Station. Closed  
#2 RSP done, and bleed valves. Pump can  
be used! Need to pull gate. B.F.

1999 295th day - 70 days follow

Replaced Control  
Transformer in Hoist  
Checks OK

Rajtan

3700 - REPACKED # 2 RSP

PAULA / Tom

KCslip4 63407

SEA431498

OCTOBER **23** SATURDAY

SUNDAY **24** OCTOBER

1999 296th day - 69 days follow

1999 297th day - 68 days follow

United Nations Day (US)

AIR-GLANCE

KCslip4 63408

SEA431499

OCTOBER **25** MONDAY

TUESDAY **26** OCTOBER

Holiday (Ireland)

1999 298th day - 67 days follow

1999 299th day - 66 days follow

0900 Delivered centrifugal pump  
Dehornish

D. Mohan

1300 - Station checklist,  
Send Alarms to W.P.  
Recharge hydro tank.  
Adjust #2 RSP packing, and seal  
water, Flushed sump.  
B.F.

KCslip4 63409

SEA431500

OCTOBER

**27**

WEDNESDAY

1999 300th day - 65 days follow

THURSDAY

**28**

OCTOBER

1999 301st day - 64 days follow

1100 - checked Station,  
R.S./B.E.

1215 - flushed out #2  
pump packing housing  
2 Years

KCslip4 63410

SEA431501

OCTOBER **29** FRIDAY

SATURDAY **30** OCTOBER

1999 302nd day - 63 days follow

1999 303rd day - 62 days follow

AIR GLANCE

KCslip4 63411

SEA431502

OCTOBER **31** SUNDAY

MONDAY **1** NOVEMBER

Halloween

1999 304th day - 61 days follow

Daylight Saving Time ends (US)

1999 305th day - 60 days follow

SEA431503

KCslip4 63412

NOVEMBER

2

TUESDAY

WEDNESDAY

3

NOVEMBER

Election Day (US)

1999 306th day - 59 days follow

1999 307th day - 58 days follow

0910 - Station checklist,  
Send Alarms, Pump down surface  
B.F.

0840 Here To Service  
Generator Batteries  
Tom Blair II

1250 - WHT INS. INSPECTION CHECKED  
PRESSURE VESSELS.  
BUFFALO BORLERS @ 88°'S.  
VERY GOOD.

1755 Five ext check (D)

NO SEADOO WHEELS EVIDENT  
IN STATION. T-P OK.

C✓.

DATA GLANCE

KCSlip4 63413

SEA431504

NOVEMBER

4

THURSDAY

1999 308th day - 57 days follow

0930 - CHECK STATION.  
CW

FRIDAY

5

NOVEMBER

1999 309th day - 56 days follow

AT-A-GLANCE

KCslip4 63414

SEA431505

NOVEMBER

6

SATURDAY

1999 310th day - 55 days follow

SUNDAY

7

NOVEMBER

1999 311th day - 54 days follow

KCslip4 63415

SEA431506

NOVEMBER

8

MONDAY

1999 312th day - 53 days follow

TUESDAY

9

NOVEMBER

1999 313th day - 52 days follow

0900

check SCADA and metrotel  
telemetry fail

Bob K

0800 change oil 3 PM  
compressor  
- Sales1545 - Get 05 West up in  
station, station check list  
D Yarn1230 - checking station  
send alarms, restock  
supplies D Yarn

KCSlip4 63416

SEA431507

NOVEMBER

10

WEDNESDAY

1999 314th day - 51 days follow

THURSDAY

11

NOVEMBER

1999 315th day - 50 days follow

Veterans Day (US)

Remembrance Day (Canada)

DATA-GRAFIC ©

KCslip4 63417

SEA431508

NOVEMBER

12

FRIDAY

1999 316th day - 49 days follow

SATURDAY

13

NOVEMBER

1999 317th day - 48 days follow

1700 - Checked Station. Reset  
high watered ALARM High flows  
still present. 1-2-3 RSP all  
on. ~~1000~~ - water finally getting a  
good flush. B.F.

■ A BLANC ■

KCSlip4 63418

SEA431509

NOVEMBER

14

SUNDAY

1999 318th day - 47 days follow

MONDAY

15

NOVEMBER

1999 319th day - 46 days follow

1130 BLEW DOWN SERVICE  
AIR SYSTEM, RAN AC'S THRU  
SEVERAL CYCLES TO  
WARM UP COMP'S, WATER  
IN AIR LINES IS FROM  
RECIPIER. S. GREENE

3:05 station deck list, send  
alarms were down pump room  
cleaned clear water glands  
full of sludge D. Yager

KCSlip4 63419

SEA431510

NOVEMBER

**16**

TUESDAY

1999 320th day - 45 days follow

WEDNESDAY

**17**

NOVEMBER

1999 321st day - 44 days follow

© AIA-GLANCE®

KCslip4 63420

SEA431511

NOVEMBER

**18**

THURSDAY

1999 322nd day - 43 days follow

FRIDAY

**19**

NOVEMBER

1999 323rd day - 42 days follow

0830 check station, run pump  
in hangar, flush out piping  
glued on pump, dumped  
trash

Q-Yellow  
ran gen truck for 15 min.

A-A-Glance®

KCSlip4 63421

SEA431512

NOVEMBER

**20**

SATURDAY

1999 324th day - 41 days follow

SUNDAY

**21**

NOVEMBER

1999 325th day - 40 days follow

AFFA-GLENCE®

KCslip4 63422

SEA431513

NOVEMBER **22** MONDAY

TUESDAY **23** NOVEMBER

1999 326th day - 39 days follow

1999 327th day - 38 days follow

1030 - station check list  
Send alarms, hose  
pump room, pump down  
W/4

D Yahr

KAI SLANCE

KCslip4 63423

SEA431514

NOVEMBER **24** WEDNESDAY

THURSDAY **25** NOVEMBER

1999 328th day - 37 days follow

1999 329th day - 36 days follow

Thanksgiving Day (US)

1300 - Checking station  
D Yarn

© AT-A-GLANCE®

KCslip4 63424

SEA431515

NOVEMBER **26** FRIDAY

1999 330th day - 35 days follow

SATURDAY **27** NOVEMBER

1999 331st day - 34 days follow

AZ-A GLANCE 8

KCslip4 63425

SEA431516

NOVEMBER **28** SUNDAY

MONDAY **29** NOVEMBER

1999 332nd day - 33 days follow

1999 333rd day - 32 days follow

1315- Check Station  
Send Alarms to W.P.  
Clean control room.  
B.F.

KCslip4 63426

SEA431517

NOVEMBER 30 TUESDAY

WEDNESDAY 1 DECEMBER

1999 334th day - 31 days follow

1999 335th day - 30 days follow

7830 - Moved gen truck  
back to Deverish  
8/1/99

KCslip4 63427

SEA431518

DECEMBER

2

THURSDAY

FRIDAY

3

DECEMBER

1999 336th day - 29 days follow

1999 337th day - 28 days follow

Hanukkah begins at sundown

14:10 Checked and tested UCL.  
Checked and cleaned station  
battery, set charges on equalizing  
charge.

Kym

1500 Hu. Checked station  
Changed red indoor drift bag

SEA431519

KCSlip4 63428

DECEMBER

4

SATURDAY

SUNDAY

5

DECEMBER

Hanukkah

1999 338th day - 27 days follow

1999 339th day - 26 days follow

KCslip4 63429

SEA431520

DECEMBER

6

MONDAY

TUESDAY

7

DECEMBER

1999 340th day - 25 days follow

1999 341st day - 24 days follow

0700 - Let contractor in station  
for flap gate work  
*D Yager*

0703 - Hawk Mech replacing flap  
gate #2  
*WB*

0700 Hawk Mech replacing  
flap gate #3  
*WB*

0710 - At station to let contractor  
in for RST flap gate work.  
Switched RST lands to 3-2-1.  
#3 RST flap gate is done.  
B.F.

1230 - Station check list  
Send a report, Tech  
with contractor  
*D Yager*

1430 - Checking station contractor  
done pump back to  
auto  
*D Yager*

KCSlip4 63430

SEA431521

DECEMBER

8

WEDNESDAY

THURSDAY

9

DECEMBER

1999 342nd day - 23 days follow

1999 343rd day - 22 days follow

0700 Hawk Mech replacing flap  
gate #1  
WB

1245. Check Station, Contractors  
done with all flap gates.  
They are cleaning up now.  
All pumps is AUTO  
BT.

AT A GLANCE®

KCSlip4 63431

SEA431522

DECEMBER **10** FRIDAY

1999 344th day - 21 days follow

SATURDAY **11** DECEMBER

1999 345th day - 20 days follow

© ABBANCE

KCslip4 63432

SEA431523

DECEMBER **12** SUNDAY

MONDAY **13** DECEMBER

1999 346th day - 19 days follow

1999 347th day - 18 days follow

1200 - station check list, send  
alarms, dump trash,  
D Yester

KCslip4 63433

SEA431524

DECEMBER

**14** TUESDAY

1999 348th day - 17 days follow

WEDNESDAY

**15**

DECEMBER

1999 349th day - 16 days follow

VERBAL

KCslip4 63434

SEA431525

DECEMBER

16

THURSDAY

FRIDAY

17

DECEMBER

1999 350th day - 15 days follow

1999 351st day - 14 days follow

2930 - checking station  
C2 water system float  
would not shut water off  
moved lever sh 3

D Yellow

1015 - CHECK station  
water float  
12/17 11:30

Safety walk through

Allen Alston

KCSlip4 63435

SEA431526

DECEMBER

**18**

SATURDAY

1999 352nd day – 13 days follow

SUNDAY

**19**

DECEMBER

1999 353rd day – 12 days follow

A-G-LANCE®

KCslip4 63436

SEA431527

DECEMBER **20** MONDAY

1999 354th day - 11 days follow

TUESDAY **21** DECEMBER

1999 355th day - 10 days follow

0850 Here to P.M.  
8 STATION

1015- Check Station. Test  
RSP<sub>S</sub>, Alarms, B.F.

#2 RSP Motor  
CAPACITOR IS BAD REMOVED  
CAPACITOR WILL ORDER  
New one Tim Ewell 11

1115- CALLED OUT ON C-2 ALARM.  
Had to recharge hydro tank.

AT-A-GLANCE

KCSlip4 63437

SEA431528

DECEMBER **22** WEDNESDAY

THURSDAY **23** DECEMBER

1999 356th day - 9 days follow

1999 357th day - 8 days follow

0800 PM start in  
Tom E.W.H.

1020- Check Station  
P.F.

ALL-A-GLANCE®

KCslip4 63438

SEA431529

DECEMBER

**24**

FRIDAY

1999 358th day - 7 days follow

SATURDAY

**25**

DECEMBER

1999 359th day - 6 days follow

Christmas Day

AVAILANCE®

KCslip4 63439

SEA431530

DECEMBER **26** SUNDAY

1999 360th day - 5 days follow

Boxing Day (A, C, NZ, UK)  
St. Stephen's Day (Ireland)

MONDAY **27** DECEMBER

1999 361st day - 4 days follow

1100 - Check-list. Sand  
Alarms, pump covers wet well  
Adjusted #3 RSP packing. Note →  
#2 RSP packing seal water  
still flowing to packing when  
pump is off. Effecting the  
CO<sub>2</sub> hydro tank. Will report.  
B.E.

KCSlip4 63440

SEA431531

DECEMBER **28** TUESDAY

WEDNESDAY **29** DECEMBER

1999 362nd day - 3 days follow

1999 363rd day - 2 days follow

Checking mech equipment lesmick

© AT-A-GLANCE®

KCslip4 63441

SEA431532

DECEMBER

**30**

THURSDAY

1999 364th day - 1 day follows

FRIDAY

**31**

DECEMBER

1999 365th day - The last day

0830 - Check Station,  
Clean Head.  
B.R.

ATA-GLENCE

KCSlip4 63442

SEA431533

1/3/002000

1200 - Misplaced new log.  
Will have it tomorrow.  
Station check list,  
Send Alarms.

B.T.

1/11/00 - Checklist

SENT ALARMS

CLEARED REST RM

Cheryl

1/12/00

0900

Crane hoist  
Review

Lisa Taylor

Jim Cerniak

Sarah Gabre

Ed Hahn

Emile Swanson

1/4/00 - Checked station  
Stacked supplies  
Cleared

1/14/00

1/14/00 Checked station

1/4/00 Exercised all RSP's  
Pumped down WW Cyl

1/10/00 Station check, change  
filters in air handling  
unit Send alarms  
D Yarns

Station check  
Roof drain plugged.  
Big ladder  
will get done after  
ladder returned

1/14/00 9:12 ENTERED STATION TO TAKE MEASUREMENTS  
FOR CRANE. ALSO CHECKED DETERIORATED RR.  
CROSSING AT ENTRANCE. LEFT STATION AT 9:45.

CHRIS FOSS

A-A-GLANCE

KCSlip4 63443

SEA431534

LEAD DN 94.9

2000 CALENDAR

Public Holidays (continued)

MT	Feb 12 Lincoln's Birthday • Nov 2 Election Day
NE	Feb 12 Lincoln's Birthday • April 22 Arbor Day
NV	Oct 31 Nevada Day
NH	April 26 Easter Day* • Nov 2 Election Day
NJ	Feb 12 Lincoln's Birthday • April 2 Good Friday • Nov 2 Election Day
NM	Feb 12 Lincoln's Birthday
NY	Feb 12 Lincoln's Birthday • Nov 2 Election Day
NC	April 5 Easter Monday* • 12 Halifax Day • May 10 Confederate Memorial Day • 20 Mecklenburg Day
ND	Feb 12 Lincoln's Birthday • April 2 Good Friday
OH	No additions to Federal List
OK	April 13 Thomas Jefferson's Birthday • 22 Oklahoma Day • Sept 16 Cherokee Strip Day • Oct 10 Oklahoma Historical Day • Nov 2 Election Day • 4 Will Rogers' Day • 26 Friday after Thanksgiving
OR	Feb 12 Lincoln's Birthday
PA	Feb 12 Lincoln's Birthday • April 2 Good Friday • June 14 Flag Day • Nov 2 Election Day
RI	May 4 Rhode Island Independence Day • Aug 19 Victory Day* • Nov 2 Election Day
SC	Jan 19 Robert E. Lee's Birthday • May 10 Confederate Memorial Day • Nov 2 Election Day • Dec 25 Second Christmas Day
SD	Feb 12 Lincoln's Birthday
TN	April 12 Lincoln's Birthday • Nov 2 Election Day
TX	Jan 19 Robert E. Lee's Birthday • March 2 Texas Independence Day • April 21 San Jacinto Day • June 19 Emancipation Day • Nov 2 Election Day
UT	Feb 12 Lincoln's Birthday • April 30 Arbor Day • July 24 Pioneer Day
VT	Feb 12 Lincoln's Birthday • March 2 Town Meeting Day • Aug 16 Bennington Battle
VA	Jan 18 Lee-Jackson Day* • Nov 2 Election Day
WA	Feb 12 Lincoln's Birthday
WV	Feb 12 Lincoln's Birthday • June 20 West Virginia Day • Nov 2 Election Day
WI	Nov 2 Election Day
WY	Feb 12 Lincoln's Birthday • Nov 2 Election Day
A.S.	April 2 Good Friday • 17 American Samoa Flag Day
GUAM	April 2 Good Friday • July 21 Liberation Day • Dec 8 Lady of Czernin Day
P.R.	Jan 6 Three Kings Day • 11 Eugenio Maria de Hostos' Birthday • March 22 Abolition of Slavery • April 2 Good Friday • 16 Jose de Oigao's Birthday • July 17 Luis Munoz Rivera's Birthday • 25 Constitution Day • 27 Jose Celso Barbosa's Birthday • Nov 19 Puerto Rico Discovery Day
V.I.	Jan 6 Three Kings Day • Feb 8 Lincoln's Birthday • April 1 Maundy Thursday • 2 Good Friday • 5 Easter Monday* • June 16 Organic Act Day • July 3 Emancipation Day • 28 Supplication Day • Oct 20 Local Thanksgiving Day • Nov 1 Liberty Day • Dec 26 Second Christmas Day
Canada	April 2 Good Friday • May 24 Victoria Day* • July 1 Canada Day • Sept 6 Labour Day* • Oct 11 Thanksgiving Day* • Nov 11 Remembrance Day

\*Monday Observance

Major Religious Observances

Jan 3 Epiphany Sunday • 6 Epiphany • 31 Septuagesima Sunday • Feb 17 Ash Wednesday • 21 First Sunday of Lent • March 1 Fast of Esther • 2 Purim • 3 Shushan Purim • 28 Palm Sunday • April 1 Maundy Thursday • 1 First Day of Passover • 2 Good Friday • 3 Holy Saturday • 4 Easter Sunday • 11 Low Sunday (First Sunday after Easter) • May 13 Ascension Day • 21 Fifth Day of Pentecost (Jewish) • 30 Trinity Sunday • Aug 15 Assumption of the Blessed Virgin Mary • Sept 11 Rosh Hashanah (Jewish New Year) • 12 Rosh Hashanah (Second Day of Jewish New Year) • 20 Yom Kippur (Day of Atonement) • 25 Succoth • Oct 31 Reformation Day • Nov 1 All Saints' Day • 2 All Souls' Day • 26 First Sunday in Advent • Dec 4 First Day of Hanukkah • 8 Feast of the Immaculate Conception
---

SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT
JAN	2	3	4	5	6	7	8	9	10	11	12	13	14
	15	16	17	18	19	20	21	22	23	24	25	26	27
	28	29	30	31				30	31				
JUL	2	3	4	5	6	7	8	9	10	11	12	13	14
	15	16	17	18	19	20	21	22	23	24	25	26	27
AUG	6	7	8	9	10	11	12	13	14	15	16	17	18
	21	22	23	24	25	26	27	28	29	30	31		
MAR	5	6	7	8	9	10	11	12	13	14	15	16	17
	20	21	22	23	24	25	26	27	28	29	30	31	
SEP	3	4	5	6	7	8	9	10	11	12	13	14	15
	17	18	19	20	21	22	23	24	25	26	27	28	29
APR	2	3	4	5	6	7	8	9	10	11	12	13	14
	16	17	18	19	20	21	22	23	24	25	26	27	28
OCT	1	2	3	4	5	6	7	8	9	10	11	12	13
	15	16	17	18	19	20	21	22	23	24	25	26	27
MAY	7	8	9	10	11	12	13	14	15	16	17	18	19
	21	22	23	24	25	26	27	28	29	30	31		
NOV	5	6	7	8	9	10	11	12	13	14	15	16	17
	19	20	21	22	23	24	25	26	27	28	29	30	
JUN	4	5	6	7	8	9	10	11	12	13	14	15	16
	18	19	20	21	22	23	24	25	26	27	28	29	30
DEC	3	4	5	6	7	8	9	10	11	12	13	14	15
	17	18	19	20	21	22	23	24	25	26	27	28	29

© 2000 BLANKS

KCslip4 63444

SEA431535